

FIG. 1




FIG. 2




FIG. 3




FIG. 4

FIG. 5




FIG. 6




FIG. 7





FIG. 8







FIG. 10



20h
52h
20h
SCENT TAB FOR
CRANKBAITS
50h
20h

FIG. 12